



Alternate Catalog No. OTPL60FP
Catalog No. 1SCA111004R1001

Description: LATE BREAK EARLY MAKE POLE

UPC No 6417019441733

Home > Switches & Disconnects > Disconnect & Safety Switches > Disconnect Switches > Rotary Disconnects

OTPL60FP Fourth pole with late-break and early make function. Mountable on the side of the switch.

Descriptors

Category	Rotary Disconnects
----------	--------------------

Specifications

Product Name	Accessories
Accessory Type	Fourth pole/Neutral
Accessory Sub Type	FOURTH POLE
Product Main Type	OTPL60
Suitable For	OTM40
Quantity / Count	1